

MacDermid Photographs from site visit


11/20/01

RCRA RECORDS CENTER
FACILITY MACDERMID
I.D. NO. CTD001164599
FILE LOC. R-10
OTHER RDMS# 100832

1) looking north from Gear Street to Huntingdon Ave.

2) shows park across East Aurora Street, north of facility, shows highway and inaccessibility of Naugatuck River

3) park again



RDMS DocID

00100832

4) through 8) shows Steel Brook and inaccessibility

9) through 13) located across the street from MacDermid - shows other potential metal sources to Naugatuck between MacDermid and river

14) and 15) from east side of Naugatuck River (convenience store parking lot North of facility) shows inaccessibility

16) and 17) shows sludge disposal area located across Huntingdon Ave from facility

18) and 19) shows rusted and crushed drums and scrap metal just north (over hill) from sludge disposal area

**US EPA New England
RCRA Document Management System
Image Target Sheet**

RDMS Document ID # 100832

Facility Name: MACDERMID INC

Facility ID#: CTD001164599

Phase Classification: R-10

Purpose of Target Sheet:

☒ **Oversized (in Site File)** ☐ **Oversized (in Map Drawer)**

☐ **Page(s) Missing (Please Specify Below)**

☐ **Privileged** ☐ **Other (Provide Purpose Below)**

Description of Oversized Material, if applicable:

PHOTOGRAPHS FROM SITE VISIT

☒ **Map** ☐ **Photograph** ☐ **Other (Specify Below)**

*** Please Contact the EPA New England RCRA Records Center to View This Document ***